






PROLINE®



OI / CWSD Cover
OI / CWSD haube
OI / CWSD Capot
OI / CWSD Tapa

1	M6-1x12	2		3	M6-1	4	M6-1x12	5	M6-1
									
(4x) (8x)		(4x) (8x)		(4x) (8x)		(4x) (8x)		(4x) (8x)	
Stainless Steel Only Nur Rostfreier Stahl Acier inoxydable Seulement Acero Inoxidable Solamente									



Stainless Steel
Edelstahl
Acier Inoxydable
Acero Inoxidable



Mild Steel
Rostfreier Stahl
Acier Peint
Acero Swave



Computer Workstation Enclosure (CWS)



NOTE: Drill required to fasten self-tapping screws, item 4
Anmerkung: Dirll angefordert, um Gewindeschneidschrauben, Einzelteil 4 zu befestigen.
Note: Dirll prié d'attacher les vis Sparker, point 4.
Nota: Dirll requerido para sujetar los tornillos self-tapping, item 4.