






SPD/SPDS/MM + CCJ06

Ref.	Pic.	Qty.
A		M5x10 12
B		M6x12 6
C		6


H	S
1200	450
1400	550
1600	650
1800	750
2000	850
2200	950







A
Torque
4-5.5 Nm



B
Torque
4-5.5 Nm




A
Torque
4-5.5 Nm




Drill
 ϕ 8

B
Torque
4-5.5 Nm




Drill
 ϕ 8
B
Torque
4-5.5 Nm

2b







SPD/SPDS/MM + SPDG01

Ref.	Pic.	Qty.
A	M6x12	8
B		6
C		4
D	20x5	2m
E	15x5	5m




All open space shall be covered with gasket







SPD/MM + SPDEG01








Ref.	Pic.	Qty.
A	 M6x12	8
B		6
C		4
D	 17x17	3 PCS 2.13 M/PCS



All open space shall be covered with gasket



SPD/SPDS/MM + CCI06/CCM04



- * - If CCM are used remove CCI from corners.
- * - If SPDG01 or SPDEG01 are mounted CCM kit can't be used.