

PC MOUNT FAST ACTING FUSE
MELTING TIME CURRENT DATA
30/35 - 30/50AMPS 600 VOLTS AC
CAT. NO. PCF (AMP)-H, R & S
GOULD SHAWMUT
NEWBURYPORT, MA 01950

720052

