




Hardware Required for Assembly (included):



**(12) 3/8-16
Carriage Bolts**




**(12) 3/8-16 Hex
Serrated Flange
Nuts**



**(4) #10-32
Screws**




**(2) #10-32
Nuts**




**(4) #12-24
Screws**


Hardware Required for Overhead Installation (not included):



(4) 1/4-20 Bolts



(4) 1/4-20 Strut Nuts



**(4) 1/4-20 Spring
Washer**

Tools required for rack assembly and overhead mounting:





Rack Assembly

Part Number: PZLRB4P6 & PZLRB4P6WH


For maximum stability:

- Panduit recommends that the mount channels be installed centered on the main brackets.
- Panduit recommends that the mount channels be installed at the widest possible spacing.





For Technical Support: www.panduit.com

Installation of Rack to Unistrut Overhead Structure



Assembly of D-Ring Panels

Part Number: PZLRB4P6LR & PZLRB4P6LRWH

Required Hardware:**#12-24 Screws**

For Instructions in Local Languages
and Technical Support:
www.panduit.com

PANDUIT
www.panduit.com

E-mail:
cs@panduit.com
Fax:
(708) 444-6448